PATENT ABSTRACTS OF JAPAN

(11)Publication number:

63-085438

(43) Date of publication of application: 15.04.1988

(51)Int.Cl.

G01N 25/72

(21)Application number : 61-232899

(71)Applicant: NISSAN MOTOR CO LTD

(22)Date of filing:


30.09.1986

(72)Inventor: KIMURA SHUJI

(54) NONDESTRUCTIVE INSPECTING METHOD FOR COATING LAYER

(57) Abstract:

PURPOSE: To compare the internal state of a coating layer by heating or cooling one member of a base material which has the coating layer and generating a temperature distribution, and comparing the temperature distribution with a reference temperature distribution. CONSTITUTION: A piston 1 which has the coating layer 2 on its crown surface 1a is installed on a turntable 4 with the crown surface 1a up so that the center of the internal surface of the crown surface 1a contacts the upper end part of a heater 3. Then turntables 4 are arrayed on plural pedestals 5 in the moving direction so that they advance as shown an arrow A, a heat image device 6 is provided above the stop positions of the turntables 4, and the temperature distributions formed on



the coating layers 2 by heaters 3 are measured in order. The heat image device 6 inputs infrared rays emitted by the coating layers 2 and outputs an electric signal. At the same time, an infrared ray from a reference temperature source is inputted and both electric signal are compared with measure the temperature distributions of the coating layers 2, whose internal states are evaluated.

LEGAL STATUS

[Date of request for examination]

[Date of sending the examiner's decision of rejection]

[Kind of final disposal of application other than the examiner's decision of rejection or application converted registration]

[Date of final disposal for application]

[Patent number]

[Date of registration]

[Number of appeal against examiner's decision of rejection]

[Date of requesting appeal against examiner's decision of rejection]

[Date of extinction of right]

Copyright (C); 1998,2003 Japan Patent Office

コーテイング層が示す基準の温度分布と比較する ことによつてコーティング層の内部状態を評価す るようにしたので、非破壊且つ非接触でコーティ ング層を検査することができ気孔はもちろん、内 部の剥離や組成むら等をも容易に短時間で正確に 知ることができる。

4. 図面の簡単な説明

第1図はこの発明の一実施例を示す説明図、

第2図乃至第4図はこの発明により得られたピス トンのコーテイング層の温度分布を例示す る熱画像図、

第5回はこの発明の他の実施例を示す説明図、

第6図は従来のコーテイング層の非破壊検査方法 を示す説明図である。

1…ピストン

2…コーテイング層

3 … ヒータ 4 … 回転台

6 … 熟画像装置


7…オイル容器


8 …熟電線

出願人 日産自動車株式会社 代理人 弁理士 大

- 7 -

第 1 図





2 EZ

B

C


B

C

SS.4 56.7 59.0 59.3 59.6 59.9 60.7C

54.9 55.2 55.5 55.8 56.1 56.4 56.7°C

第5図



96° A 187

